

# Сравнительная таблица стружколомов

## ■ Стружколомы



	ТаeguTec	Sandvik	Kennametal	Seco	Walter	Valenite	Mitsubishi	Sumitomo	Toshiba	Kyocera	Korloy	Iscar
<b>НЕГАТИВНЫЕ</b>	<b>FA</b>		FF FS	FF1		F2	FH FS	FL,FA	TF	GP DP	HU	SF
<b>КОСЫЙ</b>	<b>FG (FC) EA,SF VF,FS</b>	PF,QF LC MF	FP,FN LF	MF2	NF3 NF4	F5	SH FY,SA FJ,SY,SA	SU LU SX	TSF,ZF ZM,TS,NS 27,NM	HQ,CO, XP,VF GU,CO	VF,HF,GF	NF
	<b>ML</b>	NGP	GP-K,MS- MS GP	MF1	NS4 NS5,NS6,G1				SS,CB,17	XP MU	HA	12 PP
	<b>SU MP</b>	SM,SR,23 MM QM	P	MF3	NM4	M2	MS	EX		HU SU	HS,GS	TF VL
	<b>MC (PC) MT</b>	SM PM KF	MN MP	MR3 M3			MV MA	GU UX,UG	AS TM,CF	GS CJ PS HS	HC HM,GM	
	<b>MG- ET</b>	KM MR	UN RP UM	MG- M5	MG- NR4	M5	MG- MH,GJ	UZ MU,MX	38 DM,MG-CM 33,37 SM,SA	MG- C GT XS,HU,MS	B20,B25	MG- TNM
<b>КОСЫЙ</b>	<b>RT</b>	PR KR	RN,MG- RN	MR7	NM5,NM7 NM6,NM9	R3	GH HAS,HDS		TH,CH	ZS,GC CS,PT HT	GR	NR
	<b>RH</b>	PR QR MR	RM	R6,RR9 R4,37	NR5,NR6 NR7	R6	HZ HA HH	MP HG HP		HX	GH	RP NM
<b>КОСЫЙ</b>	<b>HT (HN) WS WT</b>	HR WF WM	RH FW MW,RW	R8,56,57 R7 W-MF2			HX,HBS HV,HDS,HXD	HU,HW	57 TU 65 AFW ASW		HH B40	
<b>ПОЗИТИВНЫЕ</b>	<b>FA</b>	PF,UF	UF,11,GM	FF1	PF4 PF5		FV	LU FP		CF DP	HFP	38,PF
	<b>FG</b>	PM,UM	LF	F1	PS4 PS5	PM3 PM4		FK SU SC,SK	PF	GP,XP DP,XQ,HQ	HMP,C05	SM 16,GT- 14,17 19,MT-
	<b>MT</b>	PR,UR	MF	F2	PM5 MT-	PM5	SQ,SV MQ,MV MT- G	SF,MU	PM	MT-	C25	
	<b>PMR- FL (WS) WT</b>	PMR- AL WF WM	PMR- HP FW MW	PMR- AL W-F1 W-F2	PMR- PM2	PMR- IL	PMR- SW MW	UJ AG LUW		GP,HQ G,PMR- AH		AF,AS WF WG
	ТаeguTec	Sandvik	Kennametal	Seco	Walter	Valenite	Mitsubishi	Sumitomo	Toshiba	Kyocera	Korloy	Iscar